

**DIVISION OF WATER RESOURCES  
JACKSON ENVIRONMENTAL FIELD OFFICE  
TRIP REPORT**

Inspection Date:

Permit Number:  County:

Owner/ Facility:

Facility Type:

Address:


Contacts/ Titles:

Name:	Micheal (Mike) Presley	Title:	Technician
Phone:	731.772.2588, ext. 2026	email:	micheal_presley@transcanada.com
Name:	Jamie Simeon	Title:	Technician
Phone:		email:	
Name:	Andrew (Andy) Fitz	Title:	Technician
Phone:		email:	

Samples Collected:  Yes ☒ No  Photos:  Yes ☒ NO

**DISCUSSION & COMMENTS**

1. Andrew Fitz will be assuming the environmental duties previously handled by Mike Presley.
2. Per Mike Presley, they still have not discharged since my August, 2009, visit. Since he was not in the office for me to review their discharge & free board measurements, he will scan & send the information electronically on Thursday, 4.18.2013.
3. The freeboard appeared to be less than 12" which is approaching a need to spray.
4. The circulation pump was found to non-operational. Per Mike Presley (MP), the plan is to replace the sump pump recirculation pump with a pump that sits on the bank. Based on my notes, this was the same situation found in 2009.
5. A flow meter to the irrigation system has been installed in response to the August, 2009 inspection.
6. The last discharge was May 26, 27, 28, 2010 at a total 3 day volume of 47,735 gallons.

Names & Signatures of inspector(s)	Agency/ Office/ Phone & Fax Numbers	Date(s)
 James W. Scott	TDEC/DWR/JEFO 731.512.1362 / (FAX) 731.661.6283	04.17.2013